

2022 URFC Roads and Water Monitoring Report

Road Maintenance Activities

As a general prescription, all mainline ridgetop roads are monitored following a significant (> 2.5" in 24 hrs) rainfall event.

Environmental Enhancement

Project Name	Type	Acres	Number of Sites or LW Structures	Cubic Yards of Sediment Delivery Prevented
Northern Mendocino County Forest Health Collaborative	Fire Resiliency/Forest Health	223	N/A	N/A
Invasive Plant Removal	French Broom	46	N/A	N/A
Riparian Reforestation	Redwood	20	N/A	N/A

Water Drafting

Site Name	Watercourse Class	Amount Diverted (Acre-Feet)
M&M Tank 2	II	.29